



Looking into sensor
connector

Bosch LSU 4.9 wideband oxygen sensor and connector

Bosch LSU 4.9 pin	Wire colour	Notes
1	Red	Connect to ECU pin APE (Fury/Thunder)
2	Yellow	Connect to ECU pin IPE (Fury/Thunder)
3	White	Connect to ECU pin HEATER (Fury/Thunder)
4	Grey	Connect to ignition switched +12V
5	Green	Connect to ECU pin MES (Fury/Thunder)
6	Black	Connect to ECU pin RE (Fury/Thunder)