


150 PSI SENSOR

Wiring looking into sensor

Pin DESCRIPTION

A	0 V
B	5 V
C	SIGNAL



Set Calibration to 1000 kPa (150psi) TI Sensor